

1/6




FIG. 1




FIG. 2

3/6

FIG. 3

300				
310	TEXT AND LINE ART			
320	RENDERING	SCREEN MODULATION	FILTERING	TRC
310	Error Diffusion	N/A	Sharpen Level 2	1
310	PHOTO/CONTONE			
310	RENDERING	SCREEN MODULATION	FILTERING	TRC
	Halftone Screen 106 lpi	N/A	Sharpen Level 2	1
310	COARSE HALFTONE			
310	RENDERING	SCREEN MODULATION	FILTERING	TRC
	Error Diffusion	N/A	Sharpen Level 2	1
310	FINE HALFTONE			
	RENDERING	SCREEN MODULATION	FILTERING	TRC
	Halftone Screen 106 lpi	50%	Descrreen Level 5	1
	320	330	340	350

The diagram shows a rectangular box representing a printing process. The box is labeled with reference numerals 400 and 410. Inside the box, the word "ROUGH" is at the top. Below it, the process is divided into four stages, each with a reference numeral below it: "RENDERING" (420), "SCREEN MODULATION" (430), "FILTERING" (440), and "TRC" (450). The "RENDERING" stage is further detailed with "Halftone Screen 106 lpi". The "SCREEN MODULATION" stage is detailed with "75%". The "FILTERING" stage is detailed with "Descrreen Level 2". The "TRC" stage is detailed with "1".

400

410

ROUGH

RENDERING
Halftone Screen 106 lpi

SCREEN
MODULATION
75%

FILTERING
Descrreen Level 2

TRC
1

420

430

440

450

FIG. 4




FIG. 5

5/6




FIG. 6

6/6




FIG. 7